

Multimeters & Panel Meters

PROVA_Series Digital Clamp-Meters

Detailed product specifications are available on: us.100y.com.tw



- Operating temp: 4°C to 50°C
- Operating humidity: less than 85% related humidity
- Altitude: up to 2000M
- Storage temp: -20°C to 60°C
- Storage humidity: less than 75% related humidity
- Dimensions: 271mm (L) x112mm (W) x46mm (H)
10. 7" (L) x4. 4" (W) x1. 8" (H)
- Weight: 647g/22. 8oz (battery included)

Part No.	Product No.	Manufacturer	Description
40954	PROVA 6600	PROVA	Clamp Meter



- Operating temp: 4°C to 50°C
- Operating humidity: less than 80% RH related humidity
- Storage temp: -20°C to 60°C (-40°F~140°F)
- Consume current: about 25mA
- Dimensions: 271mm (L) x112mm (W) x26. 2mm (H)
10. 7" (L) x4. 4" (W) x1. 8" (H)
- Weight: 647g/22. 8oz (battery included)

Part No.	Product No.	Manufacturer	Description
40955	PROVA 6601	PROVA	Clamp Meter



FEATURES

- Accurate DC/AC digital clamp meter for current measurement
- 1mADC/0. 1mAAC high resolution
- One touch zero for DCA adjustment
- 23mm diameter jaw
- Large 3 3/4 digits LCD
- Fast bargraph display (20 times/sec) for transient observation
- Max/Min and data hold functions
- Easy single rotary switch for any function selection
- Ideal for works in crowded switch box for cable areas

General specification

Conductor size	23mm max. (approx)
Battery type	two 1. 5V SUM-3
Display	3 3/4 LCD with 40 seg. bargraph
Range selection	manual
Overload indication	left most digit blinks
Power consumption	15mA (approx.)
Sampling time	2 times/sec (display) 20 times/sec. (bargraph)
Operating temperature	-10°C to 50°C
Operating humidity	less than 85% relative
Altitude	up to 2000M
Storage temperature	-20°C to 60°C
Storage humidity	less than 75% relative
Dimensions	183mm (L) x61. 3mm (W) x35. 6mm (H)
Weight	7. 2" (L) x2. 5" (W) x1. 4" (H) 190g (battery included)
Accessories	Carrying bag x 1 Users manual x 1 1. 5V battery x 2

Part No.	Product No.	Description
8303	PROVA-11	AC / DC mA True RMS Clamp Meter



- POWER: 1. 5V (UM3) *2 battery
- Current consume: 10mA
- Working temp/humidity: -10°C~50°C/85% MAX

Part No.	Product No.	Manufacturer	Description
40847	PROVA15	PROVA	AC / DC Clamp Meter



- Operating temp: -10°C~50°C
- Storage temp: -20°C~60°C
- Dimensions: 210 (L) x62 (W) x35. 6mm (H)
- Weight: 200g
- Storage humidity: < 85%R. H
- Storage humidity: < 75%R. H

Part No.	Product No.	Manufacturer	Description
44217	PROVA21	PROVA	Power Harmonics and Leakage Tester

DM_Series Digital Clamp-Meters

Detailed product specifications are available on: us.100y.com.tw



- Operating environment: 0°C~50°C
- Storage environment: -20°C~60°C
- Related humidity: <80%RH
- Dimensions: 277mm (H) x102mm (W) x49mm (T)

Part No.	Product No.	Description
13084	DM2605	3-1/2 AC/DC Clamp Meter
14408	DM2608	3-3/4 AC/DC Clamp Meter

- We provide a wide range of products to development and maintenance engineers in all type of business
- If you cannot find the components you want on the catalogue, please call us.



Taiwan: 886-3-5753170

Shanghai: 021-54151736 Shenzhen: 0755-83298787

Centenary Materials

Waiting for your phone call



T E L : Taiwan: 886-3-5753170
F A X : Taiwan: 886-3-5753172
E-mail: Taiwan: us_sale@100y.com.tw

Shenzhen: 86-755-83298787
Shenzhen: 86-755-83640655
Shenzhen: 100y@163.com

Shanghai: 86-21-54151736
Shanghai: 86-21-64605107
Shanghai: 100y-1@163.com