

Multimeters & Panel Meters

DM_Series Digital Multimeter

Detailed product specifications are available on: us.100y.com.tw



- DCV: 0~2±0.5%/20/200/600V±1.5%
- ACV: 0~200/600V±2.5%
- DCA: 0~2m/20m/200m/10A±2%
- Ω: 0~200/2K/20K/200K/2M±1%/20M±3%
- SIZE: 126x70x26mm

Part No.	Product No.	Description	Range Manual/Auto	Diode Y/N	Frequency(Hz)	Capacitance	Auto Power off Y/N	Batt. Test Yes/No	Buzzer Yes/No
2250	DM-3000	3 1/2 Digital Multimeter	Manual	Yes	No	No	No	No	Yes



Part No.	Product No.	Manufacturer	Description
28983	DM-9023	LUTRON	3 1/2 Capacitance Meter
28997	DM-9092	LUTRON	Digital Multimeter



Part No.	Product No.	Description	Range Manual/Auto	Tr.(hFE)	Diode Y/N	Frequency(Hz)	Capacitance	Auto Power off Y/N	Batt. Test Yes/No	Buzzer Yes/No
2231	DM122	3 1/2LCD Digital Multimeter	Manual	Resistance-2000M	Yes	Yes	Yes	No	No	Yes
2233	DM124	3 1/2LCD Digital Multimeter	Manual	Resistance-2000M	Yes	Yes	Yes	No	No	No



Part No.	Product No.	Description	Range Manual/Auto	Tr.(hFE)	Diode Y/N	Frequency(Hz)	Capacitance	Auto Power off Y/N	Buzzer Yes/No
8282	DM132	3 1/2 Auto-Range Digital Multimeter	Auto		Yes			Yes	
2230	DM8007	3 1/2 LCR Digital Multimeter	Manual		Yes	20MHz	200uF	Yes	Yes
25839	DM8020	Digital Multimeter		0-1000	Y	4kHz/40kHz/400kHz/4000kHz	4nF/40nF/400nF/4uF/40uF	Y	Y
9271	DM8050	4 1/2TRUE RMS Digital Multimeter	Manual		Yes			Yes	Yes

APPA_Multimeters and Accessories APPA_Series Digit Multimeters

Detailed product specifications are available on: us.100y.com.tw



Part No.	Product No.	Manufacturer	Description	Range Manual/Auto	Buzzer Yes/No	Capacitance	Auto power Y/N	Diode Y/N
8576	APPA-101	APPA	Auto-Range Digital Multimeter	Auto	Yes	4nF,400nF,4uF,40uF	Yes	Yes



- Display: 4 1/2 digit, 20000/4000 count
- Voltage: DCV : 20mV ~ 1000V ACV : 20mV ~ 750V
- Current: DCA/ACA : 20mA ~ 10A
- Resistance: Ohms : 200Ω ~ 2GΩ range
- Frequency: Hz : 20Hz ~ 1MHz
- Diode Test : 1.1mA 3.3V
- Store Recall Function : UP to 1000 record
- Continuity Test: 2KHz Tone

Part No.	Product No.	Manufacturer	Description	Frequency(Hz)	Capacitance	Weight
51918	APPA-106		The Toughest Multimeters	4KHz ~ 400MHz	4nF ~ 40mF	620g
32249	APPA-107N	APPA	The Toughest Multimeters	20Hz ~ 1MHz	4nF ~ 40mF	

